

September 28, 2023

Aisha Moyla  
Assistant Vice President  
for Facilities & Campus Engineering  
PACE University  
One Pace Plaza  
New York, NY 10038

**RE: 161 William Street, New York, NY 10038**

Dear Ms. Moyla,

We have reviewed the vibration monitoring data available for 161 William Street. The vibration monitoring data does not indicate any hazardous conditions. 161 William is structurally stable, and no hazardous conditions are present.

Very truly yours,

**Thornton Tomasetti, Inc.**



Elisabeth A. Malsch, Ph.D., P.E.  
Managing Principal