

October 5, 2023

Aisha Moyla  
Assistant Vice President  
for Facilities & Campus Engineering  
PACE University  
One Pace Plaza  
New York, NY 10038


**RE: 161 William Street, New York, NY 10038**

Dear Ms. Moyla,

We visited 161 William Street, October 4, 2023, to review the building conditions. Our observations did not indicate any signs of structural damage or crack movement was recorded for the cracks along exposure 2 (wall adjacent to 57 Ave) since April 2023. Additionally, we reviewed the vibration monitoring data available for 161 William Street. The vibration monitoring data does not indicate vibration levels that would've caused and no hazardous conditions are present.

Very truly yours,

**Thornton Tomasetti, Inc.**



Elisabeth A. Malsch, Ph.D., P.E.  
Managing Principal